

Maritime Safety Queensland
Queensland Notices to Mariners

637 (Permanent) of 2010

Maryborough pilotage area

Locality: Bullock Point, Tin Can Inlet

Activity: lighted special marks installed

Mariners are advised that two (2) lighted special marks Fl Y 4s have been installed on the seaward corner piles of the remnants of Bullock Point Jetty in Tin Can Inlet.

The marks are located in the following positions:

- latitude 25° 49.6232' S, longitude 153° 03.2346' E
- latitude 25° 49.6050' S, longitude 153° 03.2349' E.

Signs have been installed on both seaward corner piles saying “NO MOORING - KEEP OFF”.

Mariners are advised to keep clear of these jetty piles.

AUS charts affected: 240

Maritime Safety Queensland charts affected: Great Sandy Strait (South) (GSS1)

Note: latitude and longitude positions on WGS84 horizontal datum (compatible with GDA94 datum).

For further information about this notice, please contact:

The Gladstone Regional Harbour Master's office on 07 4973 1200

Authorised by: Director (Maritime Services)

Issued: Brisbane 30 July 2010