

Maritime Safety Queensland
Queensland Notices to Mariners
1201 (Temporary) of 2011



Outside pilotage areas

Locality: Carlo Creek - Tin Can Bay

Activity: Re-establishment of West Cardinal Beacon

Mariners are advised that the west cardinal beacon (Fl.W.Q9.15s) located at the entrance to Carlo Creek - Tin Can Bay has been re-established approximately 50m west due to a growing sand bar. The new position is latitude 25° 53.594' S, longitude 153° 02.429' E

Mariners are advised to navigate with caution when transiting the area

AUS charts affected: none

Maritime Safety Queensland charts affected: none

Maritime Safety Queensland Beacon to Beacon Directory 8th edition map 43,44

Note: latitude and longitude positions on WGS84 horizontal datum (compatible with GDA94 datum).

For further information about this notice, please contact:

The Gladstone Regional Harbour Master's office on 07 4973 1200

Authorised by: Director (Maritime Services)

Issued: Brisbane (Thursday, 1 December 2011)