

QUEENSLAND
NOTICE TO MARINERS
525 (Permanent) of 2009

Maritime Safety
Queensland

Queensland Transport

OUTSIDE PILOTAGE AREAS

LOCALITY: HERVEY BAY - ENTRANCE TO BEELBI CREEK, TOOGOOM

ACTIVITY: REPOSITIONING OF LATERAL MARKS

Mariners are advised that the navigation aids marking the entrance to Beelbi Creek, Toogoom have been repositioned.

Mariners are warned that the channel dries at low tide and local knowledge is needed for safe navigation.

The locations of the marks from north to south are:

- Port lateral – latitude 25° 13.2935' S, longitude 152° 40.0950' E
- Port lateral – latitude 25° 13.6450' S, longitude 152° 39.9980' E
- Port lateral – latitude 25° 13.8660' S, longitude 152° 40.0720' E
- Port lateral – latitude 25° 14.0688' S, longitude 152° 40.2093' E
- Starboard lateral – latitude 25° 14.2305' S, longitude 152° 40.3085' E
- Starboard lateral – latitude 25° 14.7130' S, longitude 152° 40.0655' E.

AUS Charts Affected: None

Maritime Safety Queensland Charts Affected: Great Sandy Strait (North) (GSS2)

Maritime Safety Queensland Beacon to Beacon Directory 8th Edition maps 27

NOTE: Latitude and longitude positions on WGS84 horizontal datum (compatible with GDA94 datum).

For further information about this Notice, please contact:

The Gladstone Regional Harbour Master's office on 07 4973 1200

Authorised by: DIRECTOR (MARITIME SERVICES)

Issued: Brisbane 4 August 2009